

FITNESS CERTIFICATE
(To be filled by the inspecting Officer)

1. Name of the officer : Anju George, Assist Engineer
LID & EW section, Mararikulam, South G.P
2. Name of school : ST. Joseph's public school, Pollethai.
3. Location with name of Education : Pollethai, Anappuzha, Cherthala
Dist./Sub Dist
4. Classification of buildings as specified in column 4 of the application for fitness certificate and size : concrete Roof
GIF = $25.32 \times 8.66 \times 3.70$
= $32.0 \times 8.66 \times 3.70$
FF = $25.32 \times 8.66 \times 3.70$
= $32.0 \times 8.66 \times 3.70$
5. Period for which the certificate is issued : 2023-24
6. Name of defect if any
a) Foundation and Basement : NIL
b) Superstructure : NIL
c) Doors and windows : NIL
d) wood work wrought and put up : NIL
e) Roof : NIL
f) Flooring : NIL
g) Miscellaneous(cracks etc.) : NIL
7. Any major defect noticed which will render the building unsafe in any manner. : NIL
NO
8. Whether maintenance work have been done properly? : yes
9. Whether the structure is sound or not for conducting classes? : Structure found safe under normal wind weather conditions

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 23/6/2023 and found to be fit / unfit
to conduct class for the period 2023-2024 for the reasons stated above.

Place : Kattoor

Signature

Anju

Date : 24/6/2023

Designation

